




SDT170 report created at Fri Aug 06, 2004 15:39

Data downloaded from device NE170040317

Point	Nr	Value	Unit	Sensor Type	Timestamp	SCFM
1	0	65.4	dBuV	Internal Sensor	Fri Aug 06, 2004 19:39	1.589
2	1	76.1	dBuV	Internal Sensor	Fri Aug 06, 2004 21:38	3.5
3	0	45.6	dBuV	Flexible Sensor	Fri Aug 06, 2004 21:33	0.589
4	0	63	dBuV	Internal Sensor	Fri Aug 06, 2004 21:33	1.589
5	0	55.4	dBuV	Internal Sensor	Fri Aug 06, 2004 21:33	1.118
6	0	58.6	dBuV	Internal Sensor	Fri Aug 06, 2004 21:33	2.178
7	0	12.5	dBuV	Flexible Sensor	Fri Aug 06, 2004 21:33	0.1
8	0	10	dBuV	Flexible Sensor	Fri Aug 06, 2004 21:34	0.118
9	0	77.6	dBuV	Parabolic Sensor	Fri Aug 06, 2004 21:34	3.5
10	0	65.7	dBuV	Internal Sensor	Fri Aug 06, 2004 21:34	2.178
11	0	68	dBuV	Internal Sensor	Fri Aug 06, 2004 21:34	2.178
Total SCFM Loss This Survey						18.637



Leak Survey Performed By: Energy Conservation Crew

Report Prepared By: Joe - Certified Ultrasound Inspector

Equipment Used: Ultrawave 170M+, Flexible Sensor, Internal Sensor, Parabolic Sensor

Equipment Calibrated: Yes